

**AC/DC mA True RMS Clamp Meter**

**MODEL PROVA 11**

- Super High Resolution  
DC 1mA,  
AC 0.1mA
- One Touch Zero for  
DCA
- True RMS



**PROVA 11**

**Specifications for PROVA 11**

Range	Output	Accuracy	
DCA 0-4000mA	1mA	+/- 1.5%rdg +/- 5dgts	
DCA 0-30A	10mA	+/- 1.5%rdg +/- 3dgts	
ACA 0-400mA	0.1mA	+/- 1.5%rdg +/- 5dgts	True RMS
ACA 0-4000mA	1mA	+/- 1.5%rdg +/- 8dgts	True RMS
ACA 0-30A	10mA	+/- 2.0%rdg +/- 5dgts	True RMS
DCV 0-400V	0.1V	+/- 1.0%rdg +/- 3dgts	
ACV 0-400V	0.1V	+/- 2.0%rdg +/- 5dgts	True RMS

**Power Source:**

2 X 1.5V AA UM3 Batteries

**Current Consumption:** 10mA

**Operating Condition:**

-10°C to 50°C at 85% max. RH